


How to Field-Measure a Plant Floor for CAD Layout Updates

By Chase A. Kramer

ChaseKramerEngineering.com



Reasons to keep an accurate floor layout

Safety & compliance

- Emergency egress routes, fire lanes, and exit paths need to be current for OSHA compliance and actual life safety in an emergency.
- Equipment clearances (electrical panels, machine guarding zones) must match what's really on the floor, not what was planned two years ago.
- Forklift/AGV traffic patterns and pedestrian walkways need accurate documentation to prevent incidents.

Operational efficiency

- Material flow optimization, you can't fix bottlenecks or reduce travel distance if the layout drawing doesn't match reality.
- Capacity planning for new equipment or lines depends on knowing what space is available.
- Lean/continuous improvement initiatives (5S, value stream mapping) rely on an accurate baseline.

Cost & planning

- New equipment installs need accurate existing conditions to avoid costly surprises (utility conflicts, clearance issues).
- Facility expansion or reconfiguration decisions get made off these drawings; inaccuracies compound into expensive mistakes.
- Insurance and facility valuation sometimes reference these documents.

Cross-functional coordination

- Maintenance needs accurate utility/equipment locations (electrical, pneumatic, compressed air drops).
- Quality/engineering needs to know cell boundaries for process control documentation.
- New hires and contractors use the layout to orient themselves quickly.


Audit & documentation trail

- ISO 9001, IATF 16949, or other quality system audits often check that documentation reflects actual conditions.
- Insurance audits and fire marshal inspections reference these too.

Guidelines

This method I'm about to talk about works the best when your plant's orientated in cardinal directions.

- Make it easy to remember which way is in what direction in your plant, say, North is the entrance and South is the back door.
- When you take a measurement from a pole, always use the surface near to the center of the pole. Thickness of pole will be disregarded for speed.
- You will always need one **North/South** and **East/West** measurement, unless you're doing relative measurements around something you already measured.
- You should use walls as measurement bounds if you trust their placement on the CAD and they're accessible to your laser or tape.
- Check with your manager for the degree of accuracy required. $\pm 6''$ is very reasonable for a basic layout update.
- Use concrete relief cuts originating from your support beam as bounds for your measurements instead of relying on the beam entirely.
- Always measure to the surface of the beam in the **circle** and avoid anywhere else unless you take note of the method change.
- Always draw objects in CAD as simple as possible, or it will be difficult to find where you measured to. (Boxes)



What you'll need


- Tape measure
- Laser level




- Notepad
- Laser distance measurer (Useful to get under machines and for far distances) (Also to avoid a measuring wheel)




Example




Note that the bottom left corner of the welder machine is Southeast of the pole. With this, we already know we need a South and East measurement.




Take your second measurement. Using your concrete relief cuts as a tape pull start will make this possible. Or using your laser level, centered in the column, will do the same job.



Put a dot between your measurements. This will tell you this isn't an object dimension.



Take down your object dimension and make a figure of where you measured to, for clarity.



If your object is far away from your column axis, you'll need to use your laser level to pull the column's center to your object. Measuring from the column isn't possible in this situation, so using the floor reliefs and your laser level is required.

Wrap up

Simple CAD knowledge and the Line tool will help you locate each object. A machine dense 200,000 square feet factory floor can be completed in about 4 weeks using this method.